



3/6




FIG. 3A





FIG. 3B

ILTs 20 and die pad 39
being made same thickness
as OLTs 12



4/6




FIG. 4




FIG. 5




FIG. 6




FIG. 7A




FIG. 7B




FIG. 8



6/6




FIG. 9




FIG. 10